

bottom and Judder cleaned. Gammind and Jucorahd.  
ow down to wear and tear.

25 MAR 1925

by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

EL'S NAME Stl. Sc. K. "LABRADOR". Rpt. Bdx. No. 3469

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report. 24/5/92.)

of Survey

The Bordeaux Surveyors report this vessel placed in dry dock, bottom cleaned and coated and minor repairs effected.

A proposal to carry out the 2nd s.s. No.1 due 4-25 at Bordeaux about the end of the present year has been agreed to.

It is submitted the vessel appears worthy to remain as classed with record of survey 3-25 as recommended.

100 A1 Ship Transfer  
3.75 Bdx.



© 2021  
25.3.25.

Lloyd's Register  
Foundation

W660-0038