

Rpt. 12.

Copy.
FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port *Nest Hartlepool.* (When received in London Office)

Vessel's Name *S.S. Banka*

Official No. _____ No. in Reg. Book _____

Port of Registry (For Foreign Vessels) *Amsterdam*

Iron or Steel *Steel* State whether Classed by Lloyd's Register *Yes*

Name of Owners *Stoom Maatschappij Nederland* Date of Verification *23rd Feb 1914*

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line *8' 10"* *269* *q/m* *ins.*

From centre of disc to top of statutory deck line }
at awning or part-awning deck } *ft.* *ins.*

Fresh water line above centre of disc *7 1/2* *19* *q/m* *ins.*

Indian Summer line above centre of disc *6 1/2* *17* *q/m* *ins.*

Winter line below centre of disc *6 1/2* *17* *q/m* *ins.*

Winter North Atlantic line below centre of disc *ins.*

Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of *wood or* iron deck with the vessel's side }
at main, spar or upper dk. *ins.*
at *shelter* awning or pt. awning dk. *1 1/4* *4* *q/m* *ins.*

NOTE.—It should be clearly shown whether the statutory deck line is set off from a ~~wood~~ or iron deck.

(Signed) William M. Ward Surveyor.

(To be filled up in London Office.)

Statement No. *23520* Date of Committee's Minute *6.2.14*

Moulded Depth for record *36* *ft.* *0* *ins.*

Freeboards compared and found correct by _____ date *24.2.14*

Is fee paid? *new vessel* Form for Certificate *Issued by Dutch Govt.*

Instructions _____ date _____

Certificate written *Issued by Dutch Govt.* Noted for posting

*Classification 100% shelter deck
Conditional on the above freeboards*