

No. of Donkey Boilers 2

Managers

Stowage in Main

in Donkey

Last Report

Particulars of

CHARACTER

Date of last Survey

Periodical Survey

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

Carrying Tonnage

100 A1-1

1.6 Feb. 2nd

COPY.

# Lloyd's Register of Shipping.



Port Copenhagen

15<sup>th</sup> March 1932

This is to Certify that I have

Surveyed the Propeller and Reconnections with fastenings of the Boiler and Machinery of the Ship S. TROPICO 6805

of Genoa 4277 Tons, while the vessel was lying on pontoon at the Yard of Messrs S. Burmeister & Wain's Maskin- og Skibssbyggeri, Copenhagen

and that I SHALL have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I WILL have

Recommended that the record of LMC - with date

be continued in the Register Book in the case of this vessel.

S. Clausen.


Engineer Surveyor to Lloyd's Register.

Surveyors are required to fill in the space for Committee's Minute.

Survey Fee (per Section 24, B 1.) - 10m. 11. 20.

Special Damage or Expense (per Section 24, B 1.) - 10m. 11. 20.

Travelling expenses (if chargeable) - 10m. 11. 20.



Lloyd's Register Foundation

Engineer Surveyor



COPY.

# Lloyd's Register of Shipping.

1/2 Tropic  
Apr. 4th. No 8739.

Port Copenhagen

15th March 1932



This is to Certify that I have

Surveyed the steel screw bark vessel "TROPIC" of Denmark, 6805 tons gross, while on passage at Messrs Carlsberg & Søn, Copenhagen, Denmark effecting temporary repairs to shell plating.


and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs temporary

recommended by me have been completed to my satisfaction, and that I ~~have~~ <sup>will</sup> recommend that she be continued as classed

2/100 A1 and have record of survey 3.32 subject to a new lower section of plates weight and not being placed on board and shall plate D (22) being permanently repaired at the first convenient opportunity the vessel being fit to carry passengers in bulk.

Signed: - J. Sanderson  
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, detail, or negligence of the Surveyors, or other Officers or Agents of the Society.



W623-0029