

REPORT ON BOILERS.

No. 18968.

17 OCT 1928

6-9-28
 te of writing Report 6-9-28 When handed in at Local Office 8th October 1928. Port of Greenock
 No. in Survey held at Greenock Date, First Survey 22nd November 1924 Last Survey 8th October 1928.
 eg. Book. M/S "Winton" (Number of Visits ☒) Gross Tons ☐ Net Tons ☐
 on the Greenock
 Built at Greenock By whom built W. Hamilton & Co. Ltd. When built 1928
 ilers made at Greenock By whom made Bochuan & Co. Greenock Ltd. When made 1928
 oners The Avenue Shipping Co. Ltd. Port belonging to London

VERTICAL DONKEY BOILER— No. one Description Vertical Manufacturers of steel —
 ade at — By whom made — When made — Where fixed Engine Room Working pressure 100
 sted by hydraulic pressure to — Date of test — No. of Certificate — Fire grate area — Description of safety valves Double Spring
 o. of safety valves 2 Area of each 1.767 Pressure to which they are adjusted 105 If fitted with easing gear yes If steam from main boilers can
 ter the donkey boiler ✓ Dia. of donkey boiler — Length — Material of plates — Thickness — Range of tensile
 length — Descrip. of riveting long. seams — Dia. of rivet — Whether punched or drilled — Pitch of rivets —
 ip of plating — Per centage of strength of joint — Rivets — Working pressure of shell by rules — Thickness of shell crown plates —
 adius of do. — No. of Stays to do. — Dia. of stay — Diameter of furnace Top — Bottom — Length of furnace —
 hickness of furnace plates — Description of joint — Working pressure of furnace by rules — Thickness of furnace crown
 plates — Radius of do. — Diameter of uptake — Thickness of uptake plates —
 hickness of water tubes —

See further particulars in attached report No. 48193

For further particulars see attached report

The foregoing is a correct description,

Manufacturer.

Dates { During progress of
 work in shops - - }
 Survey { During erection on
 while board vessel - - - }
 building { Total No. of visits

See Machinery Report

Is the approved plan of boiler forwarded herewith Yes

10. GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)

This boiler now securely fitted on board
This Report accompanies that of the Machinery

Survey Fee ... £ ✓ : When applied for, 19...
 Travelling Expenses (if any) £ ✓ : When received, 19...

W. Gordon-Mitchell
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute GLASGOW 16 OCT 1928

Assigned *See accompanying report*



Lloyd's Register
 Foundation

W663-0168