

Gross Tonnage  
Less Crew Space  
Less above Crown of  
Engine Room ...  
Tonnage for Free

250,914.

F.E.

73381

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "SWEDEN MARU" Rpt. Kobe No. 2780

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 79

Depth "d" 16.0'

Framing: Table No. 3

Description Bulb angle as approved.

Longitudinal No. 30415

Proportions  $\frac{\text{Length}}{\text{Depth}} =$  10.7

Awning

Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A-1. (steel) "Awning Dk with freeboard," as recommended. The Summer freeboard of 9'-3½" from centre of disc to top of statutory deck line at Awning deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 Dks (steel) & Awning Dk. (steel)

Cell DB 334' 1118t. FPT 126t. APT 23t.

FK. Collision BH. to Awning Dk 5 BH. to upper Dk. Gen. Lloyd's A/C.P.

W668-0080

Spacing  
BEAMS, Bridge De  
Tee Bu