

2-3
Bonesinker 2-2 1/2" ✓

4" ✓

Connected to condenser or to circulating pump

Yes ✓

Is a separate Donkey Suction fitted in Engine

W678-0083

room bulk

cf "War Sorel".

It is submitted the Newcastle Surveyors should be requested to forward their report on the Howden Boiler marked :-

9089
Lloyd's Test
370 lbs.
9.5.18
W.F.A.

also fitted on board this vessel.

The Hartlepool Surveyors should be requested to forward their report on the Howden Boiler marked :-

3500
yds Test/-
370 lbs.
W.F.
9.5.18

also fitted on board this vessel.

Ref 15510 sent ✓



© 2021

Lloyd's Register
Foundation

in part top Thickness of plates crown Description of longitudinal joint
bottom bottom plates Material Thickness: Sides Back