

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl & M.V. PECTEN Rpt. hwc No. 81433**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.")

Transverse No. 91.75Depth "d" 28.16Framing: Table No. ✓Description Bull angle frames as approvedLongitudinal No. 40370Proportions Length 13.44
Depth =~~Deck~~ Sheerstrake

as approved.

de Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1. (Steel) "Carrying Petroleum in Bulk"
1 D* (Stl) "Longitudinal framing at bottom and at deck"
Cell D.B. v E 73' 291 t, D.T. f 32' 369 t, F.P.T. 199 t, A.P.T. 70 t.
F.K, 15 B.H, pt Cem, Lloyds A & C.P.
P 99', B 41', F 63'. "machy aft"



© 2019

Lloyd's Register
Foundation

W68-0129

10.6.27.