

(2m, 8, 4.)

1.

Sent to Chief Surveyors 8. 11. 04

Received from Chief Surveyors

VESSEL'S NAME S. L. "Saint Irene."

Report Gls. No. 22247.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st entry

When due

± 100 A1. ("Steel").

10k (SH). 2 to B & deep framing.

TRB = Cell DB a. 108' u B & B 44' f 146' 859t. FPT 101t. APT 44t.

FK. 6 BH. Cem. Lloyd's A & CP.

P 32'. B 204'. F 34'.

J. H. T.
8/11/04

C. K. J.



© 2020

Lloyd's Register
Foundation

W681-0095