

Engine Room ...
Gross Tonnage 301.66

Depth "d" ...

5c.1.14.

F.E.

Received by Chief Ship Surveyor 31.8.14

Received from Chief Ship Surveyor

VESSEL'S NAME *Sheela Walpole*

Rpt. *Steel*

No. 27862

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 36.45

Depth "d" 11.75

Framing: Table No. 3 page 9

Description

Single Angle as approved

Longitudinal No. 4921

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.3$

Deck Sheerstrake .56 of an inch instead of .38 as required

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \star 100A-1. (Steel) Ocean Trawler, as recommended

\star 100A-1. (Steel) Ocean Trawler

15K

BK 7 1/2 4BH. Can. Lloyd's Reg. Q 74' F 21'



© 2020

Lloyd's Register
Foundation

W692-0051

DECK, SECOND DECK, Single Angle, Bulb,
Angle, Plate, Tee Bulb, or Channel)
Spacing

Deck. Material & thickness
Poop Deck Stringer Plate, breadth & thickness