

LENGTH on Deck as per Rule	Ft.	Ins.	BREADTH Moulded	Ft.	Ins.	DEPTH, ACTUAL—Top of Floors to top of Awn. or Shelter Dk. Beams	Ft.	Ins.	No. of Decks with flat laid
400		0	53		45	Do.	32	7	2
						Upper Deck Beams	23	10	No. of Tiers of Beams 2

1m, 8, 21.

Wreck 6013

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *S.S. "Histleben"*

Rpt. *Sld.*

No. *28857*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long.
Transverse No. *13700.*

Depth "d" *33'*

Framing: Table No. *4*

Description *Channel frames as approved.*

2nd
Longitudinal No. *35048.*

Proportions Length = *11.42*
Depth

Deck Sheerstrake *as approved.*

This vessel received damage through striking quay wall, 5 shell plates and 2 frames have been faired in place.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **+ 100 A1 (Stel)** with freeboard," as recommended. The Summer freeboard of *3'-1"* from centre of disc to top of statutory deck line at ——— deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 Dks (Stel.)

Cell D.B. 347' 12497. F.P.T. 2317. A.P.T. 2667.

F.K. 6 B.H. (Collision bulkhead to weather deck) com. Lloyd's A.K.P.F. 36'

It is concluded the steel wire hawsers are as approved and not as stated but the Surveyor should state if this is so. The Surveyor should be requested to state the number of breast hooks fitted and the dates of the Secretary's letters as these have been omitted from the Report.

Angles on upper edge *7" x 3" x 36*
Spacing *27" x 24" respectively 48*

Tie Plates
Deck. Material and thickness *Steel* *34*

3 1/2	60
x	44
3 1/2	44
1/2	58
x 6	58
ays,	37
	44
	39
x	40
x 3 1/2	40
x 3	40
ays,	37
	35
	34

W 693-0030

