

3m, 8, 21.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Stat S.S. CONISTON*

Report *Riv*

No. *82966*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____

* 100-A-1. (Steel)

1 DK (Steel) "Well Deck"

FPT 45E, APT 24E

FK, 3BH, Conn, Plyths A & P, Q 79' B9' F9' Machy Off.

Date of build 9.21.



© 2021 *3-7-22*

Lloyd's Register
Foundation

W693-0143