

COPY.

Lloyd's Register of Shipping.



Port Port Natal

18th. October 1934.

This is to Certify that

Alexander Hargreaves Boyle

the undersigned Surveyor to this Society did at the request of Messrs. Wm. Cotts & Co. Ltd. and the Master, survey 4 lengths of steel Auxy. Feed Pipe and one length of steel Auxy. Steam Pipe, of the S.S. "ALBERT I C" of Liverpool, 18,940 Tons Gross, whilst afloat at Port Natal on the 17th. October 1934 and subsequently on account of reported defects to same.

On examination the undersigned found the 4 lengths of Auxy. Feed Pipe pitted through in places, and the length of Auxy. Steam Pipe badly wasted generally.

It was recommended that the 4 lengths of Auxy. Feed Pipe be electrically welded where pitted through and the Auxy. Steam Pipe renewed.

The above repairs were efficiently carried out and on completion the Auxy. Feed Pipes were tested to 500 lbs. per sq. in., and the new Auxy. Steam Pipe to 660 lbs. per sq. in., all being found sound under the above pressures.

Surveyor to Lloyd's Register
of Shipping.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."