

W402 - 0173

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Ferro-Concrete Dumb Barge "CRETEDYKE" Report Lon No. 82171.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the entry should contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the points presented in the endorsement." -- Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

FIRST ENTRY.

RETAIN

This vessel appears to have been built in accordance with the approved plans and it is submitted may be classed
*Al "Coasting United Kingdom (except West Coast, Cork to Pentland Firth) and Continent from Brest to Hamburg", "Subject to Annual Survey", and subject to the notation "Experimental" being made in the Register Book.

*Al. "Coasting United Kingdom (except West Coast, Cork to Pentland Firth & Continent from Brest to Hamburg".
"Subject to Annual Survey".
"Experimental."

1 Dk. FK. 4 BH. Lloyd's A & C.P. FPT 27t APT 27t.

CEB
3.10.19.

M dcs.
27. 9. 19

It is concluded, the arrangement of Pillars is as approved, but the Surveyors should be requested to state if this is so, and also to state if the fore & aft peaks have been fitted as under bulkhead tanks or if so whether they have been tested as required & also to state the capacities of these tanks.

The arrangement of Pillars, brackets & counterforts has been carried out in accordance with the approved plans Nos 163 & 89/4

© 2021 Lloyd's Register Foundation