

the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers

Donkey Boilers

or is it

2 FLS
S. G. A. H.
Submitted this Report - be attached to the
1st Entry report on the vessel.
J. H. S.
5.10.14.

© 2021
Hul 3014

Lloyd's Register
Foundation

W 705-0035