

well as broker
pending per-
caused by Coal
No. 1 due
readings are

0.615.

COPY. FOR LONDON OFFICE.

Lloyd's Register of Shipping.



Port WELLINGTON

7th MAY, 1924.

This is to Certify that I have

Surveyed the S.S. "NGAHERE", G.R. 1090-TONS, and No. 28506 IN THE REGISTER BOOK OF THE SOCIETY, FOR OCCASIONAL SLIPPING SURVEY AND REPAIRS TO STOKEHOLD BULKHEAD, PILLARS IN HOLD AND FLOORS.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be ELIGIBLE TO REMAIN AS CLASSED WITH FRESH RECORD OF SURVEY, 5/24.

being fit to carry DRY AND PERISHABLE CARGO IF SUFFICIENTLY DUNNAGED.


Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

The tank
to in the ne
ee's attentio
use of this n
the hull of a
d discharging
seconds (whi
nued -
TO LLOYD'S R
WELLINGTON

B-3m, 3, 23. T.



W703 - 0121