

She was commenced in July 1914, was launched on the 30th April 1919, and has recently been completed (last date of survey, 4th October 1920).

No. of Tiers of Beams		No. of Tiers of Beams	
alter Dk.	Round up of Uppermost Dk. Beam, Actual ..	1/4 vins	
Inches. Size in Ship.	Inches. Spacing in Ship.	Inches. per Rule. Or as Approved.	Inches. per Rule. Or as Approved.
spacing	3 2 3/4	60	60

W710-0117

2m.9.20.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. MONTE GRAPPA Rpt. Tri. No. 4863.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry.

Before this case receives consideration the Surveyors should be requested to state, whether the breadth given for E strake is correct in view of bolts being only quadruple riveted, if the thickness of F strake at ends is as approved or as given in report, & whether the figures given for spacing of rivets in edges are the number of rivets in each row between the frames. They should be informed that in future cases the actual spacing of the rivets in inches should be given as requested in report

See cable
received 23/11/20

M
AEB.
17-11-20



© 2020

Lloyd's Register Foundation

thickness