

Hull Report No. 30,425

OF HULL.

11th. March. 1918.

W.H. Roberts, F.L. Sturgeon, P. Fitzgerald, & M. Blackwood.

have surveyed during construction the hull, engines, and boiler and auxiliary machinery of H.M. Trawler, "GEORGE WESTPHALL", built by Messrs. Cochrane & Sons., Ltd., at Selby, and that the hull, machinery and other equipment have been constructed in accordance with the requirements of Lloyd's Register of Shipping and all materials and workmanship are good and that the undersigned will recommend that the vessel be classed 100.A.1. "Steam Trawler".

The whole of the work covered by the specifications and drawings except where otherwise approved as well as alterations and additions subsequently approved by the Admiralty have been carried out and completed to the satisfaction of the undersigned'.

Principal Surveyor.

Surveyors.

Ellbright.

W. K. Roberts
Frank A. Stinger
P. Fitzgerald.
M. Blackwood.

Committee's Minute
Character assigned

FRI. MAR. 15 1910

100 P.I. Beam Trawler

Lloyds A & Co

+ L.M. 3:18

VRSERS AND W		Bres
Length and Size supplied.		Te
Length.	Cir.	Stee
Fathoms.	Ins.	To
60	6	MAN
60	5	

ing Gear, Hand Co
in efficient working or
on Forecas
er? steel flaps
it above deck? fl
8 9 4 one 24

g and efficient? *Yes*

No. 4 Hatch *✓*

o. of Crutches *dec*
140 BR. 43x

5
loyd's Register of Ships

th the case).....
3-8-14.

ing plate to frames, but
y countersunk in the p
ing? *a few*

ests. *Satisfac*
do

generally
are good.

Date of issue

W710-0260

© 2020 Roberts
60 Lloyd's Register of Shipping
Lloyd's Register
Foundation