

Landing on No 2 keel plate caulked. The third length of bilge keel

3,500,11,20.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

17 JUN 1921

VESSEL'S NAME

Steel Sc. "VOLUNDE".

Rpt.

Hfx.

No. 1355

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Halifax Surveyor reports this vessel has been placed on the Marine Railway, bottom and rudder cleaned and coated, port bilge keel faired in place, and the riveting and caulking overhauled.

It is submitted the vessel appears worthy to remain as classed with record of survey.

100A.1.

5-21 Hfx

(10A)



© 2021 16. 6. 21.

Lloyd's Register Foundation

W 718-0157