

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

21 FEB 1941

VESSEL'S NAME

"PORT WELLINGTON"

Rpt. Syd

No. 17939

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

The 2nd S.S. No. 1, due 10.40, has been commenced.

The SYDNEY Surveyors report (29.10.40) the vessel placed in dry dock and the bottom coated.

The Master stated the Special Survey would be completed at a U.K. port.

It is submitted the vessel appears worthy to remain as classed with record of survey 10.40.

100A1
Shelter dk with fbd
10.40 Syd



S.S. PT HELD.

Note The vessel has since been reported a casualty.

14.2.41
© 2020



Lloyd's Register
Foundation

W 72-0002