

W730-0088

Drach 149

F.E.

56.8.12.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Rpt.

No. 1892

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

Transverse No. 82.25

Depth "d" 18.3'

Framing: Table No. *3/240/5*

Description Gull angle as

Longitudinal No. 31255

Approved

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.14$

Bridge Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **+** 100 A-1. ("Steel") as recommended.

† 100 A. 1. (Steel)

1 V. (ott) "Cantilver framed typeide tanko"

77B: Bull DTB a 129 n 8 + 133 f 161 10/6E, top side tanks
240' 15/6E FPT 95E APT 155E

FK. 6 BH. Gum Arayas at 60. P33 B105 F35

Lloyd's Register
Foundation