

screw shaft now been drawn and examined? 20 Is it fitted with continuous liner? or two liners?


s/s "War Casco"

This vessel's machinery was constructed under Special survey, at Toronto & installed at Victoria, B.C., and is in accordance with the Rules & satisfactorily reported upon. The Society's Surveyor at Philadelphia now reports that he has examined the pipe arrangement for the main boiler, a new feed pump has been fitted & the internal feed pipes rearranged etc & he recommends the record + LMC 11.18. as recommended by the Vancouver Surveyor.

It is submitted that
this vessel is eligible for
THE RECORD. + LMC 11.18. F.D.

Subject to the Water tube boilers being surveyed Annually

LM



W745-0144