

Equipment No. 4499.

Residence *Abberdeen*going to *Abberdeen*

F.E.

Dry Dock

Weeks with F

ers of Beam

Round of L

Inches in S

4 1/2 x 1

7 1/2 x 1

6 x 1

6 x 1

3 3/4

3 1/2 x

1 1/2 x 1/2

Inches in Ship

Inches in Ship

9

4 4

5 4

5 4

23-15

3 x 3

4

Mild

P. Fine

Received by Chief Ship Surveyor *6.1.02*

Received from Chief Ship Surveyor

VESSEL'S NAME *Lt. Steam Trawler "Ben Edra"* Report *Alm.* No. *7035*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>7/16" in lieu of 7/8"</i>	<i>Not required.</i>
Spar Sheerstrake . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>Ordinary.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ 100 A1 ("Steel") "Steam Trawler"* as recommended.

*+ 100 A1 ("Steel")**"Steam Trawler"**1 DR.**N.B. = DTF 86**AK 7 1/2" 3 BH Cam. Lloyd's A & CP**C.H.B.*  
*6/1/02*

WEB FRAMES, In After Body, No. and Spacing  
" " " Brdth. & Thickness  
" " " Brdth. & Thickness  
" No. of Side Stringers " "

W.T. BULKHEADS

PARTITION "

LONGITUDINAL,

© 2021

W757-0141

Lloyd's Register

Foundation

1 if wood

FFEN