

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 16 MAR 1917 When handed in at Local Office 16 MAR 1917 Port of LIVERPOOL

No. in Survey held at Birkenhead Date, First Survey Mar 8 Last Survey Mar 10 1917  
Reg. Book. 1st 4 on the Wood, Iron or Steel S. S. Wapello Master  
Tonnage: Built at Newcastle By whom Armstrong Whitworth & Co. 1912. 4.  
GROSS 5576 Owners W. J. Smith. Mgr. Port belonging to London.  
UNDER DEK 4816 Owners' Address  
NET 3268 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? D D K Name of Dock Birkenhead D K Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet;  
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 76128 Port Luv

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys. Year Assigned and expired. Machinery and Boiler Surveys (including date of N.B., if any).

100 A1 - 8.16 Club 8.16  
Carrying Petroleum in bulk. 11.16 11.16  
Society's Freeboard (if assigned) as painted on Ship and now verified

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Docking on account of mishap to propeller.  
Vessel examined in drydock, bottom, sternframe & rudder found in order. (The bottom was recoated last month).

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								
PRESENT CONDITION OF THE								
Decks	good	Stringers	✓	Inner Bottom Plating	✓	Dblg. Plates under Sounding Pipes	✓	Copper, or Y.M. of Wood Vessels (State if on Fell.)
Caulking of Decks	✓	State if Tanks have been examined inside	✓	State if Tanks now tested	✓	Engine Room Skylights	good	When put on, Month
Waterways	✓	Bulkheads	✓	Ceiling	✓	Coal Bunkers, Open'gs, Lids, &c.	✓	Boats
Roamings	✓	Cement or Asphalt (State which.)	✓	Rudder	good	Scuppers	✓	Masts, Yards, &c.
Beams & Fastenings	✓	Steering gear and its connections	✓	Windlass	✓	Cargo Hatchways	✓	Condition, how ascertained (State if wedges removed)
Outside Plating	good	Have Pumps now been examined and found efficient?	no	Have Sluice Valves now been examined and found efficient?	no	Hatches	✓	Sails
Caulking of ditto	✓	Have Watertight Doors now been examined and found efficient?	no	Have Watertight Doors now been examined and found efficient?	no	Planking of Wood Vessels	✓	Equipment letter
Stivets	✓					Caulking	ditto	Anchors, No. of
Breasthooks & Crutches	✓					Treenails	ditto	Cables (State if now ranged)
Transoms	✓					Breasthooks & Stems	ditto	length (on board)
Frames	✓					Transoms, Pointers, & Crutches	ditto	Rule length
Reverse Frames	✓					Timbers of Frame at openings	ditto	Hawser & Warps
Floors	✓					Ditto ditto at other places	ditto	Standing & Running Rigging
Keelsons	✓					Stringers, Clamps & Shells	ditto	
						Salting (State if examined.)	ditto	

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,10," or "to remain as classed and to have record of survey, 1,10, and the notations of ss No. 1-10 and ptnd10, &c."

This vessel as far as seen is in good and efficient condition & eligible to remain as classed & to have fresh record of survey 3. 17. Btk.

Survey Fee (per Section 28) £  
Special Damage or Repair Fee (if any) (per Sec. 29) £  
Travelling Expenses (if chargeable) £  
Second Surveyor's Fee (if any) £

Fees applied for,  
19  
Received by me,  
19

Committee's Minute

Character Assigned

LIVERPOOL

16 MAR 1917

100 A1

Carrying petroleum in bulk  
Subject to repairs &c.

Surveyor to Lloyd's Register of British & Foreign Shipping



Lloyd's Register  
Foundation

W763-0102