

Im. 12.15.

F.E.

Received by Chief Ship Surveyor 4. 10. 17

Received from Chief Ship Surveyor

VESSEL'S NAME

Steelss "Wan Clover"

Rpt.

Bel

No. 7867

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report (24/5/92).)

RETAIN

Transverse No.

83.

Depth "d"

27.42

Framing: Table No. 3. page 16

Description

Bulb Angle as approved

Longitudinal No.

33200

Proportions

Length

= 10.25

Depth

Bulge Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100.A.1. (Steel) as recommended.

1.DK (Steel)

Cell DB 345' 11066. F.P.T. 1186 A.P.T. 1856

FK. 7 BH. pt. Cen. Lloyd axep.

P 49. B 113' F 38'

M
4. 10. 17



© 2019

Lloyd's Register
Foundation