

GENERAL REMARKS—(continued).

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop 49.25 ft., R.Q.D. _____ ft., Bridge 112.7 ft., Forecastle 38.2 ft. (in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given as should appear in the Register Book) 124 (all)

Official No. 140353; Signal Letters _____ State if Machinery is fitted aft no

How are the surfaces preserved from oxidation? Inside Paint & Portland Cement Outside Paint

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors.

Where Fitted.	*Length. Feet.	Water Capacity. Tons.	Where Fitted.	*Length. Feet.	Water Capacity. Tons.
Double bottom, aft,	<u>126</u>	<u>275</u>	Fore peak tank,		
Double bottom, under Engines and Boilers,	<u>39</u>	<u>151</u>	After peak tank,		<u>118</u>
Double bottom, if under Engines only,			Deep tank, aft,		<u>185</u>
Double bottom, if under Boilers only,			Deep tank, forward,		
Double bottom, forward,	<u>180</u>	<u>580</u>	Other tanks, if fitted,		
Total capacity of double bottom		<u>1106</u>	(If necessary, furnish further information by sketch.)		

* The wells are not to be included in the lengths of the tanks. 345

State whether the above have been tested as required by the Rules yes

Order for Special Survey No. 618

Date 1st Feb 1917

No. 521 in builder's yard.

DATES of Surveys held while building

1917 Mar 14-16-19-27 Apr 3-13-16-23-25-27 May 1-3-8-10-11-16-24 June 4-8-12-14-21-25-27 July 2-3-6-9-11-25-28-31 Aug 1-3-4-8-9-14-16-28-30 Sept 4-10-11-12-13-17-18-19-20

Total No. of Visits 51

Surveyor's Signature

E. O. Kendall

© 2019

Lloyd's Register Foundation