

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 20 January 1914 When handed in at Local Office 19 Port of Melfaro
 No. in Survey held at Melfaro Date, First Survey 15 January Last Survey 15 January 1914
 Reg. Book. 257 on the Wood Iron or Steel Trawler "Weigelia" Master Bochrane & Sons
 (No. of Visits)

TONNAGE:-

GROSS 262UNDER DECK 239NET 103Built at SelbyOwners SouthernOwners' Address Records

(if not already recorded in Appendix to Register Book.)

By whom Bochrane & Sons

ST Co Ltd

Records

When 1911Port belonging to Melfaro

Surveyed At or in Dry Dock? Slipway Name of Dock in Melfaro Destined Voyage Fishing
 WB=CellDBorDBa feet; uE&B feet; f feet; feet;
 total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thickness of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 239 Port Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
☒ for Special Survey.
 Date of last Survey and of Periodical Surveys.

Years Assigned now original.

Machinery and Boiler Surveys (including date of N.B., if any).

100 A1
Str Trawlers
7-11

7-11

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?
 Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Annual
Vessel placed on Slipway Bottom Cleaned
Hammered, and recoated Rudder, and
steering gear Hammered

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fairied or Repaired								
Fairied or Repaired in place								
PRESENT CONDITION OF THE	Stringers <u>Good when repaired</u>	Dblg. Plates under Sounding Pipes <u>Good</u>	Copper, or Y.M. of Wood Vessels (State if on Felt)	Decks <u>Good</u>	Engine Room Skylights <u>Good</u>	When put on, Month Year	Boats <u>Good</u>	
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.	Waterways	Scuppers	Condition, how ascertained	Masts, Yards, &c.	
Coamings	State if Tanks examined	Cargo Hatchways	(State if wedges removed)	Coamings	Hatches	Sails	Equipment letter	
Beams & Fastenings	Bulkheads	Hatches	(State if wedges removed)	Beams & Fastenings	Planking of Wood Vessels	Equipment letter	Equipment letter	
Outside Plating	Cement or Asphalt (State which.)	Caulking	Equipment letter	Outside Plating	Rudder	Equipment letter	Equipment letter	
Caulking of ditto	Rudder	Treenails	Equipment letter	Caulking of ditto	Steering gear and its connections	Equipment letter	Equipment letter	
Rivets	Windlass	Breasthooks & Stemson	Equipment letter	Rivets	Have Pumps now been examined and found efficient?	Equipment letter	Equipment letter	
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches	Equipment letter	Breasthooks & Crutches	Have Sluice Valves now been examined and found efficient?	Equipment letter	Equipment letter	
Transoms	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings	Equipment letter	Transoms	Have Watertight Doors now been examined and found efficient?	Equipment letter	Equipment letter	
Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places	Equipment letter	Frames	Stringers, Clamps & Shells	Equipment letter	Equipment letter	
Reverse Frames		Salting (State if examined.)	Equipment letter	Reverse Frames		Equipment letter	Equipment letter	
Floors			Equipment letter	Floors		Equipment letter	Equipment letter	
Keelsons			Equipment letter	Keelsons		Equipment letter	Equipment letter	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,1,1" or "to remain as classed and to have record of survey, 1,1,1, and the notations of ss No. 1-11 and ptND11, &c."

This vessel appears in a good, & efficient condition
, and in my opinion is eligible to remain as
now classed with record of Survey 1-11

Survey Fee (per Section 28)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 28)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute

Character Assigned

FRI. JAN. 23. 1914

100 A1
Str Trawlers



Lloyd's Register
 Foundation

W765-0020