

REPORT of SURVEY for REPAIRS, &c.

Date of Report 3.3.17 When handed in at Local Office 3.3.17 Port of Hull
 No. in Reg. Book. Survey held at Hull Date, First Survey Jan 25 1917 Last Survey Feb 27 1917
 in Support the Wood, Iron or Steel J. J. "STOCK FORCE" Master

TONNAGE:-
 GROSS 732
 NET 362
 Built at Dundee By whom Dundee S.R.C. Ltd When 1916
 Owners W.S. Kenningh H.C. Port belonging to Whitehaven
 Owners' Address

Surveyed Afloat or in Dry Dock? Both Name of Dock Earle's Slip & Victoria
 WB=CellDBorDBa feet; uE&B feet; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.
 Last Report, No. Port
 Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? no damage Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of 1st Entry:
 Casings have been riveted up and caulked, and the rigging and mast wedges of Mizzen mast have been completed.
 Particulars of Reg. Lines and Lounges sent to Dundee, and also attached hereto.

For the purpose of fitting stern tube and sea connections vessel was placed on slip. The bottom, rudder &c were also examined and found in good condition.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Fell.)
Caulking of Decks	State if Tanks have been examined inside	Caulk Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Steering gear and its connections	Treenails ditto	Equipment letter
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	" (on board) size
Floors		Stringers, Clamps & Shelves ditto	" Rule length size
Keelsons		Salting ditto	Hawser & Warps
		(State if examined.)	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptn11, &c."
 This vessel is now in a good and efficient condition and is eligible in my opinion to be classed as recommended in Dundee 1st Entry Report.

Survey Fee (per Section 98) £ : : Fees applied for, 19
 Special Damage or Repair Fee (if any) £ : : Received by me, 19
 Travelling Expenses (if chargeable) £ : :
 Second Surveyor's Fee (if any) £ : :
 Committee's Minute
 Character Assigned 1000

19.31.
 A.S. 4
 FRI. 9-MAR. 1917
 Surveyor to Lloyd's Register of British & Foreign Shipping.
 Matthew Blackwood
 © 2020
 Lloyd's Register Foundation