

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 27.12.12 When handed in at Local Office 27.12.12 Port of Swansea  
 No. in Survey held at Swansea Date, First Survey 19/12/12 Last Survey 23/12/1912  
 Reg. Book. 566 on the Wood, Iron or Steel &c VOLMER (No. of Vols) 2 Master B. J. Rasmussen

## TONNAGE:-

GROSS 138

UNDER DECK 117

NET 803

## Built at

Swansea

## Owners

(L. H. Carl. Mgrs)

## Owners' Address

If not already recorded in Appendix to Register Book.

## By whom

Lunderland S.B.C. When 1905

## Port belonging to

Copenhagen

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Albion

Destined Voyage Mediterranean

WB=CellDBorDBa

feet; u&amp;B

feet; f

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 13827 Port

Sch.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER.  
 \* for Special Survey.  
 Date of last Survey and of  
 Periodical Surveys.

Years  
 Assigned  
 Surveyed.

Machinery and Boiler  
 Surveys  
 (including date of N.B. if any).

-1-100A1

11-11

S.S. L. 20-1-04

-L. 17-12-09

B. 59 41

TS. 11.11

Society's Freeboard (if assigned) as  
 painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? ☒ Was a damage report made by anyone else? If so, by whom? ☒

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

Now done: Vessel placed in dry dock, bottom keel & rudder cleaned examined & recoated, Rudder lifted & rebushed.

## SUMMARY OF DAMAGE REPAIRS:-

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								
PRESENT CONDITION OF THE								
Decks	Good	Stringers	Not end	Dblg. Plates under Sounding Pipes	✓	Copper, or Y.M. of Wood Vessels	✓	(State if on Fell.)
Caulking of Decks	"	Inner Bottom Plating	"	Engine Room Skylights	Good	When put on, Month	Year	
Waterways	"	State if Tanks have been examined inside	No	Coal Bunkers, Open'gs, Lids, &c.	✓	Boats	Good	
Coamings	"	State if Tanks now tested	No	Scuppers	"	Masts, Yards, &c.	"	
Beams & Fastenings	Not end	Bulkheads	Not end	Cargo Hatchways	"	Condition, how ascertained	from ch	
Outside Plating	Good	Ceiling	"	Hatches	"	(State if wedges removed)	No	
Caulking of ditto	"	Cement or Asphalt	"	Planking	of Wood Vessels	Sails	✓	
Rivets	"	Rudder	Good	Caulking	ditto	Equipment letter	P	
Breasthooks & Crutches	Not end	Steering gear and its connections	"	Treenails	ditto	Anchors, No. of	3-1-1	
Transoms	"	Windlass	"	Breasthooks & Stemson	ditto	Cables (State if now ranged)	No	
Frames	"	Have Pumps now been examined and found efficient?	Not end	Transoms, Pointers, & Crutches ditto	ditto	length	size	
Reverse Frames	"	Have Sluice Valves now been examined and found efficient?	"	Timbers of Frame at openings	ditto	Rule length	size	
Floors	"	Have Watertight Doors now been examined and found efficient?	"	Ditto ditto at other places	ditto	Hawser & Warps	Sufficient	
Keelsons	"		"	Stringers, Clamps & Shells	ditto	Standing & Running Rigging	Good	
				Salting	ditto			
				(State if examined)				

## General Observations, Opinion as to Class, Recommendation, &amp;c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,10," or "to remain as classed and to have record of survey, 1,10, and the notations of ss No. 1-10 and ptnd 10, &c."

This vessel so far as seen is in an efficient condition and is eligible in my opinion to remain as classed with fresh record of survey 12-12

Survey Fee (per Section 20)

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for,

10

Received by me,

10

Committee's Minute

Character Assigned

TUE. DEC. 31. 1912

Surveyor to Lloyd's Register of British &amp; Foreign Shipping.

Lloyd's Register Foundation

W781 - 0119