

W.D. = Cells  
total capaci  
H.M. - All  
If the con  
of the tank

21 DEC 1816

of Surveyors 21. 12. 16

Received from Chief Surveyors \_\_\_\_\_

S NAME M. S. Rinaldo

Report SA

No. 1191

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/502.)

Survey S.S. No 2

When due 9. 16 repairs

*The Hull Surveyors should be advised*

*J.W.D.*

*M*

21. 12. 16

*In SA shell to note  
+ work shell.*  
*[Signature]*



© 2019

Lloyd's Register  
Foundation

W 289 - 0013

Special Damage  
(per Sec.)