

Lloyd's Register of Shipping.

(Report on Vessel No. "19" Port Galveston, Texas.)

S. S. "NATENNA"

No. 2127

SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned Iron or Steel Forgings or Castings manufactured by *Wheeler Metal Foundry Co* of *Wheeler, W Va* for the Vessel No. *245*, being built by *Patent Steel Co* of *Orange, Texas* have been inspected by me as set forth below and found to be, so far as can be seen, *sound*.

Mark on Forgings or Castings.

Lloyd's

No. 2127

2459 SHF

Ja H. H. H. H.
Since

STERN FRAME.

RUDDER FRAME.

STEM.

Material* ...
 How made ...
 Dimensions ...
 Progress on Inspection ...
 Date when Inspected ...

CASTINGS.

Tests on Standard Test Pieces.

Tensile Test—

Tens per square inch

Extension per cent.

Cold Bending Test—

Angle before fracture

Drop Test—

Height from ground ...

Hammering Test—

If made according to Rules and found satisfactory ...

10000 72000
30 26
130° 105°

90

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

See 15th
6th

Fee (if any chargeable) £

To be paid at

Pittsburgh

© 2020

Lloyd's Register

* If of Iron, state whether scrap or puddled Iron. If of steel, state whether made on the Open Hearth process.