

1.

Sent to Chief Surveyors 17. 1. 05.

Received from Chief Surveyors _____

VESSEL'S NAME S.S. "Glenpark."

Report Grk. No. 14167

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

When due _____

± 100 A1 ("Steel")

1 BK (Stl) & web frames. "Well deck."

WB = DBa 55' f 50'. IPT 50t. APT 22t.

BK 7". 4 BH. Cem. Lloyd's A & CP.

Q 154'. Bon Q 18'. F 30'.

J. H. T.
17/1/05.

C. J.



© 2020

Lloyd's Register
Foundation

W797-0040