

Received by Chief Ship Surveyor 9/8/13

Received from Chief Ship Surveyor _____

VESSEL'S NAME

At Barge Polly Bridge Rpt. At No. 26880

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

27.67

Depth "d"

8.33

Framing: Table No.

2 page 3

Description

Ordinary, as per Rule

Longitudinal No.

3836

Proportions

Length =

11.08

Depth =

~~Deck~~ Sheerstrakeas per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\pm 100 A-1$. (Stat) Barge for being tored, as recommended.

$\pm 100 A-1$. (Stat) Barge for being tored

1/2" (Att)

FK. 5 B.H. Gen., Lloyd's A + B



© 2021
R.B.H.

11/8/13
Lloyd's Register
Foundation

W802-0001