

by Chief Ship Surveyor

3/10/10

Received from Chief Ship Surveyor

SHIP'S NAME

Stt SS 'Nora'

Rpt.

Aut

No.

8963

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Transverse No.

46.146

Depth "d"

12' 9"

Framing: Table No.

3 page 10

Description

Bulk angle

Longitudinal No.

9598

Proportions

Length

Depth

= 9.25

Deck Sheerstrake


✓

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed + 100A1 (Steel) recommended.

+ 100A1 (Steel)

12" (stt)

WB = Cull 1732 47 u 623 f 90 2134 F.P.T.H.I.E. A.P.T.214
FR. H.B.H. Cmn. A.V.C. P.25 B.60 F.26



© 2021

Lloyd's Register
Foundation

W811-0084