

3m, 12, 12.

1

Received by Chief Ship Surveyor 25. 3. 13

Received from Chief Ship Surveyor

VESSEL'S NAME

Sta. S. K. "Pamela"

Rpt.

Hul.

No. 25983.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through

grounding

now repaired as follows:-

See Abn. Rpt. 11048.

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	2						
Removed and faired or repaired.....	8	2					
Faired or repaired in place.....	29	2					

Other items:-

Vessel examined in dry dock, bottom recoated.
Rudder & Stump frame renewed. Steering gear & shafts
overhauled & repaired & minor repairs effected.

ering T

It is submitted the vessel is worthy to remain as classed with
record of Survey 3. 13 Hul as recommended.

100A.1. Stm. Trawler,
3. 13 Hul.



© 2021

Lloyd's Register
Foundation

W816-0111