

Surveyed Afloat or in Dry Dock? *Bark* Name of Dock *Slipway No 1* Destined Voyage *...*
WR-Call D.R. and D.R. feet. u. E & R feet. f feet. i

2m. 12. 12.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

St. J. Kirkland

Rpt. *Mil*

No *2530*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

S.S. No. /

The *12* S.S. No. / has now been held, and the following repairs done due to wear and tear:- *minor repairs.*

It is submitted the vessel is worthy to remain as classed, with record of Survey *6.13* and notation of S.S. *Not-13* as recommended.

*100 A1 Steam Trawler
6.13 Mil
St Mil Not-13*