

2m,7,16.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Shells Munisla

Rpt.

Actual

No.

9

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

100A1 (Steel) For River St. Lawrence & Coasting

Service to the West Indies.

1 Dk. steel.

Cell DE 208'.617t. FPT 227t. APT 11t.

FK. Intermediate bulkhead in fore hold dispensed

with 3.BH only. A&CP. P62. F39. Mch. aft.

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.

16
31



© 2020

Lloyd's Register
Foundation

W863-0104

Service to West Indies