

Tonnage Opening Fitted

Condition of Class.

NAME OF VESSEL.. TASSO

Extract from Freeboard verification of marking form received
from the.....NEWCASTLE ON TYNE Surveyors dated the.27.1.38.....

Moulded depth 17 ft.6 ins.

Corresponding draught 17 ft.0 ins.

Moulded depth as shown
on draught sheet. 17 ft.6 ins.Tropical freeboard 0 ft.3 $\frac{3}{4}$ ins.

Summer " 0 ft.8 ins.

Winter " 1 ft.0 $\frac{1}{4}$ ins.W.L.L. " 1 ft.2 $\frac{1}{4}$ ins.Fresh Water allowance 4 $\frac{1}{4}$ ins. $\frac{1}{2}$ " above the under surface of
marked from xxxx/steel under deck.

Checked by.....

Date.....19 FEB 1938



© 2019

Lloyd's Register
Foundation

W87-0100

Side Keelsons, No. each side

thickness of Intercoastal Plate...