

No. 9686.

*State if Report is also sent on the Machinery of the Vessel*

Yes.

Register Tonnage as cut on Beam... }	4700.00	Destined Voyage		Surveyed while Building, Afloat, or in Dry Dock	1/12
---	---------	-----------------	--	---	------

<b>LENGTH</b> on Deck as per Rule	Ft.	Ins.	<b>BREADTH</b>	Ft.	Ins.	<b>DEPTH, ACTUAL</b> —Top of Floors to top of Awn. or Shelter Dk. Beams	Ft.	Ins.	No. of Decks with flat laid
409		9	Moulded ..	53	2½	Do. do. Upper Deck Beams ....	34	4	240
							28	9	No. of Tiers of Beams
Dimensions of Ship per Register,									
Length	410.15		breadth.	53.7		depth.	34.23		Awn. or Shelter Dk. Moulded depth, ft. 37 ins. 1½ To Awn. or Shelter Dk. Round up of Uppermost Dk. Beam, Actual ..
						Upper Deck.	28	4½	124 ins

[illegible]







GENERAL REMARKS—(continued).

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop ☒ ft., R.Q.D. ☒ ft., Bridge ☒ ft., Forecastle ☒ ft.  
(in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated ☒

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given as it should appear in the Register Book) *1 Mk (SH) + Shelter Mk (SH). Web frames + longitudinal framing*

Official No. *137541*; Signal Letters

State if Machinery is fitted aft *no*

How are the surfaces preserved from oxidation? Inside *Paint + Cement*

Outside *Paint.*

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors. *Cell. Mk.*

Where Fitted.	Length. Feet.	Water Capacity. Tons.	Where Fitted.	Length. Feet.	Water Capacity. Tons.
Double bottom, aft,	<i>143</i>	<i>574</i>	Fore peak tank,	<i>19.7</i>	<i>27</i>
Double bottom, under Engines and Boilers,	<i>45</i>	<i>201</i>	After peak tank,	<i>18.0</i>	<i>105</i>
Double bottom, if under Engines only,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Deep tank, aft,	<i>50.0</i>	<i>1098</i>
Double bottom, if under Boilers only,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Deep tank, forward,		<input checked="" type="checkbox"/>
Double bottom, forward,	<i>166</i>	<i>598</i>	Other tanks, if fitted,		<input checked="" type="checkbox"/>
Total capacity of double bottom		<i>1313</i>	(If necessary, furnish further information by sketch.)		

\* The wells are not to be included in the lengths of the tanks *584*

State whether the above have been tested as required by the Rules. *yes*

Order for Special Survey No. *1161*

Date *17th May 1915*

No. *650* in builder's yard.

DATES OF SURVEYS held while building

*1915: July 5, 9, 21, 26. Aug 4, 10, 25. Sep 7, 8. Oct 13, 15, 20. Dec 20. 1916: Jan 5. Mar 1, 15. Apr 11, 17, 20, 26. May 4, 8, 10, 15, 17, 22, 26, 31. June 7, 13, 15, 22, 25. July 6, 11, 18, 20, 25, 28. Aug 8, 14, 18, 23, 29. Sep 1, 13, 15, 20, 25, 27. Oct 2, 6, 11, 16, 18, 20, 26. Nov 1, 7, 13, 14, 16, 18, 20, 22, 25, 28. Dec 1, 14, 21, 23, 18, 19, 27, 1917: Jan 5, 10, 16, 18, 22, 25, 31. Feb 2, 5, 7, 9, 12, 14, 15, 19, 23, 26, 28. Mar 5, 9, 13, 14, 15, 19, 21, 22, 23, 26, 27.*

Total No. of Visits *104*

Surveyor's Signature

Lloyd's Register Foundation