

Dia. of Cylinders 29" - 42" - 60" - 86" Length of Stroke 57" Revs. per minute 70 Dia. of Screw shaft as per rule 17.3" as fitted 18.25" Is the screw shaft fitted with a continuous liner the whole length of the stern tube Is the after end of the

Copy.

Glen Line (McGregor Gow & Co) Ltd,
1 & 2 East India Avenue,
LONDON.E.C.

13th April, 1916.

Messrs. R. & W. Hawthorn, Leslie & Co. Ltd,
HEBBURN.ON.TYNE.

Dear Sirs,

S.S. "GLENOGLE" - Damaged Bedplate.

On the instructions of our Chairman we referred to Lord Pirrie the question as to whether the suggested repair should be accepted or a new casting made. We enclose copy of wire received from His Lordship from which you will see that he approves generally of proposed repair but would like to see some slight alterations in executing same. You will no doubt communicate the contents of this wire together with enclosed sketches to the Wallsend Slipway Company as soon as possible in order to avoid further delay.


Trusting you will be able to effect the repair on the lines indicated in Lord Pirrie's wire.

We are, dear Sirs,

Yours faithfully,

(Sgd)

FOR GLEN LINE (MCGREGOR GOW & CO.) LTD.



© 2020

Lloyd's Register
Foundation

W876-0061