

1m, 1, 12

1

Sent to Chief Surveyors

18.7.12

Received from Chief Surveyors

VESSEL'S NAME

SS Indrakuala

Report

Jo

No.

31657

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey

First Entry

When due

+ 100 A.1 (Steel)
2 D¹² (SH)

N.B. Cell 2Ba 118' u E 13 75' f 195' 1260t F.P.T 98t A.P.T 58t
F.K. 7 BH C.m. Layer A 16 P P 80' B 148' F 80'

W.H.W.
18.7.12

Electric light
! Rep...



© 2019
Lloyd's Register
Foundation

W9-0071