

2m, 7, 16.

Wreck 16 WRECK BOX No. 16 (Bottom)

1 OCT 1916 1

Received by Chief Ship Surveyor 12. 10. 16

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S. S. Fulvia Rpt. Cff No. 39076

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE.

Damage through Heavy weather

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

Vessel examined in dry dock
Some started rivets at keels of frames renewed
Minor repairs effected

It is submitted the vessel is worthy to remain as classed with record of Survey 10-16 as recommended

100-A-1
10-16 Cff



© 2020 Lloyd's Register Foundation

Transfer Ink