

Surveyor examine all the mountings of the Main Boilers?

Shaft now been drawn and examined?

Is it fitted with continuous liner?

# REPORT, &c., FOR OUTPORTS.

Port of Sull.

Name Brika

Brig 15381 & 15/76.

Bas 9456.

Nol 4206

Plans (midship and longitudinal)


Month & Date 3.11.76.

Time

By

Ed

Returned to the London Office as soon as the contents thereof have been noted.



© 2020

Lloyd's Register  
Foundation

W11A-0144