

Wreck.

WRECK BOX
No. 7. Bottom.

Received by Chief Ship Surveyor 4.7.14

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sk "Canada" Rpt. Bou. No. 64**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/5/92.)

Nature of Survey Condition

This vessel has been examined on a slipway and found in good condition.

It is submitted the vessel appears worthy to remain as classed with record of survey 5.14, as recommended.

100A1" Steam Trawler
5.14 Bou.

M. W. W.



© 2020

Lloyd's Register
Foundation

W918-0019