

Do. of excess of Hatchway
Do. above Crown of }
Engine Room .. }
Cross Terrace

1

Sent to Chief Surveyors 10.6.09

Received from Chief Surveyors

VESSEL'S NAME *S.S. "Broomhill"*

Report *Spel.*

No. *13717*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24.6.02.)

Nature of Survey

When due

No ceiling has been fitted on the tank top under the hatchways of this vessel, and the Builders were therefore requested to obtain the Owners' consent to this omission, and the vessel was classed on the 8th June, subject to this being done.

The Builders have now forwarded a letter from the Owners consenting to the omission of the ceiling.

It is submitted the vessel might now be allowed to remain classed without special conditions.

*C. H. J.
15/6/09*

The Certificate of Classification to have the following words written on it: "Subject to the vessel being engaged exclusively in carrying coal, ore, or wood, while without cargo battens"



© 2020

Lloyd's Register Foundation

W924-0027

WEB FRAMES