

Received by Chief Ship Surveyor 3/10/12

Received from Chief Ship Surveyor _____

VESSEL'S NAME M.H. "Denise"

Rpt. Sld

No. 25473

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 5H-25

Depth "d" 15.08

Framing: Table No. 3 page 10

Description Bulk angle as

Longitudinal No. 14099

approved

Proportions Length = 10.39
Depth = _____

Budg Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100A-1. (Stub) as recommended

\pm 100A-1. (Stub)

1 Dr. (Stub) Mill deck

WB. hull Dra 81 u 3 x B 26 f 107 H 606 FPT 656 A PT 1704

FK. HBH Conn Lloyd's a x 6 P 22 Q 73 B 56 F 22

3/10/12
© 2020
3/10/12