

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 7. 12. 1914 When handed in at Local Office 7. 12. 1914 Port of GRIMSBY

No. in Reg. Book Survey held at GRIMSBY Date, First Survey and Last Survey 3. 12. 1914

105 on the Wood, Iron or Steel L. R. BIRCH Master

TONNAGE: - Built at Beverley By whom Cook, Welter & Gemmel Ltd When 1912

GROSS 215 Owners H. Grant Port belonging to Grimsby

UNDER DEK 193 Owners' Address

NET 106 (if not already recorded in Appendix to Register Book).

Surveyed in Dry Dock? Yes Name of Dock Fish Destined Voyage

WB = Cell DBor DBa feet; uE&B feet; f feet; f feet; f

total capacity tons. FPT tons; APT tons; MT feet tons.

N.B. - All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 8953 Port Grimsby

CHARACTER, Date of last Survey and of Periodical Surveys.

1-100A1 Steam Trawler 713

Machinery and Boiler Surveys (including date of N.B., if any).

1-L.M.C. 4. 12.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

caution

How Done: - Vessel placed in dry dock: Bottom cleaned, examined & recoated.

M/M Box 935

SUMMARY OF DAMAGE REPAIRS: -

Plates. Frames. R. Frames. Floors. Beams. Str. Plates. Dk. Plates. Other Items: -

Renewed

Removed and Faired or Repaired

Faired or Repaired in place

PRESENT CONDITION OF THE

Decks good

Caulking of Decks

Waterways

Coamings

Beams & Fastenings

Outside Plating

Caulking of ditto

Rivets

Breasthooks & Crutches

Transoms

Frames

Reverse Frames

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt (State which.)

Rudder good

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Dblg. Plates under Sounding Pipes

Engine Room Skylights good

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking ditto

Treenails ditto

Breasthooks & Stemson ditto

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shelves ditto

Salting ditto

(State if examined.)

Copper, or Y.M. of Wood Vessels (State if on Felt.)

When put on, Month Year

Boats good

Masts, Yards, &c.

Condition, how ascertained from DH.

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of 2 B. 1 K.

Cables (State if now ranged)

length size

(on board)

Rule length size

Hawser & Warps

Standing & Running Rigging good

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: - "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,1,1," or "to remain as classed and to have record of survey, 1,1,1, and the notations of ss No. 1-11 and ptND11, &c."

This vessel is eligible, in my opinion, to remain as classed, and to have fresh record of Survey 12. 11. 14.

Survey Fee (per Section 25) £ : : Fees applied for, 19.

Special Damage or Repair Fee (if any) £ : : Received by me, 19.

Travelling Expenses (if chargeable) £ : : Gloofounon

Second Surveyor's Fee (if any) £ : : Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute

Character Assigned

FRI. DEC. 11. 1914

10001

Stm Trawler

Lloyd's Register Foundation

W935-0016