

Engine R
Gross Ton
Less Crew S
Less above C
Engine R
TONNAGE R

F.E.

Received by Chief Ship Surveyor 19. 8. 03

Received from Chief Ship Surveyor _____

VESSEL'S NAME Ste. S.S. "Amiral P'Herminie" Report Sed No. 21460

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .	✓	✓
Description of Framing:— <u>Ordinary</u> (viz., ordinary, deep, zed, channel or bulb-angle).		


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed † 100 A 1 ("Steel") as recommended.

† 100 A 1 ("Steel")

1 DR (Ste) "Well Deck".

N.B = FPT 146 APT 66

BK 6 3/4" 4BH Cen. Lloyd's A9CP 962' 87' F17'



C.A.P.
19/8/2021



Lloyd's Register
Foundation

W440-0037

WEB