



Lloyd's Register of British & Foreign Shipping,

Ferménédjiler, Yeni-Han, Galata,

Constantinople, September 18th 1914

LOYD'S REGISTER
LONDON
1 OCT 1914

W. MUMFORD,
ENGINEER SURVEYOR.

Sir,

I am enclosing two photographs showing the damage to the steamer "CRAIGFORTH" caused by a mine, and now under temporary repairs at Buyuk-dere Bay.

I am, Sir,

Your obedient servant,

W. Mumford

The Secretary
Lloyd's Register
London.



© 2020

Lloyd's Register

Foundation

Handwritten notes and stamps in the bottom right corner, including "OCT 1 1914" and other illegible markings.

Referred to the Chief Ship Surveyor.

OCT 1 1914

Also for Mr. S. A. Hill to note:

6.6.14
1.10.14

rsa

Handwritten signature


THE SECRETARY
LLOYD'S REGISTER
LONDON.

BY-APPOINTMENT

OCT 1 1914

© 2020

Lloyd's Register
Foundation



RECEIVED
OCT 1 1914

RECEIVED
OCT 1 1914

RECEIVED
OCT 1 1914

TELEGRAPHIC ADDRESS: LLOYD'S REGISTER, LONDON.

PRINTED AND PUBLISHED BY THE SECRETARY, LONDON.