

UNDECKED 1918
 Owners' Address (if not already recorded in Appendix to Register Book)
 Surveyed Afloat or in Dry Dock? *Yes* Name of Dock *Harbour St.* Destined Voyage *Admiral Transport*
 WB=CellDBorDBa feet: *wE&B* feet: *f* feet: *1* Particulars of Classification (which must be in Book & Supplement)

*Please attach to Mr. H. H. Hartlepool
 11, North Street, West Hartlepool, Co. Durham, N.E. 10 6 0.*

LLOYD'S REGISTER WEST HARTLEPOOL.
 LONDON.

REQD MAY 24 1917
 ANSB

31st May, 1917.

David M^cAuslan

the Owner's Superintendent, survey the steel screw steamer
 "BOLDWELL", of London, 3112 tons register, on the 30th April
 1917 and subsequently, while the vessel was in Messrs. Irvine's
 S.B. & D.S. Co's Harbour Dry Dock at West Hartlepool for the
 purpose of ascertaining the damage stated to have been
 sustained through touching the ground at Rocheford on 18th
 March, 1917.

For further particulars see Log Book.

Upon Examination found:-

The paint on bottom badly scraped all fore and aft, and the
 after bulb plate of Port Bilge keel buckled.

Recommended:- the bottom be cleaned and recoated and the
 caulking of same be overhauled and made good; the bulb plate
 of bilge keel be renewed.

All the disturbed work be recoated, and the repairs be
 carried out in such a manner as to place the vessel in the
 same good and efficient condition as she was in previous to

Machinery and Survey (including date of)
 + L M
 M S 4
 B. S. 6
 T
 1) as 3 ft.
 purpose and why
 under
 (renew
 es.
 status
 coals
 of strake
 of Wood Vessels
 (Felt.)
 Month
 ascertained
 ages removed
 or
 3 B. 1 S
 (if now ranged)
 (if removed)
 the
 the
 ing Rigging
 ter Book consequ
 ed and to have
 in, to
 imel
 has been
 Foreign Ship



© 2020
 Lloyd's Register
 Foundation

now subject

W 949-0092

1918

Owners Address (if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock? *yes* Name of Dock *Harbour St.* Destined Voyage *...*

WB=CellDBorDBa capacity tons. FPT tons. APT tons; MT feet; f feet; tons. Particulars of Classification precisely as in Register

S.S. "BOLDWELL" (2)

the damage being sustained.

Fee:- 22-3-0

David McAislan
Surveyor to Lloyd's Register.

CRITERIA
1 Survey, survey and of Surveys.

A.1.
6.
23-4, 14.
6, 16.

rd (if assigned, ip and now veri

ices for this p
no
L...

om the
elfport
in pla

his wa
al wa

:-
of 4°

ems :-

Copper, or Y.M.
(State if on
When put on,

Boats.....

Masts, Yards, &
Condition, how a
(State if rec

Sails.....

Equipment lette

Anchors, No. of

Cables (State if
.. length.....
(or Bo
.. Rulo lengt

Hawser & Warp

Standing & Run

l in the Regist
main as classe

y of pin
the to
ship

old
of British & I

W949-0291 3/2



© 2020 Lloyd's Register Foundation

now Subject

