

250,7,13.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

27071

VESSEL'S NAME

St. S. Dalgarth Force

Rpt.

Dun

No.

7801

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

41.36

Depth "d"

11' 0"

Framing: Table No.

3 para 9

Description

As approved

Longitudinal No.

7238

Proportions

Length

12.96

Depth

Main

Deck Sheerstrake

As per Rule.

A Report has been received from the Hull Surveyor stating that the Survey has been completed at this Port.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \div 100 A.1 (Steel) as recommended.

\div 100 A.1 (Steel)

1 Q¹⁻¹⁴ Hull "Mill deck"

W.D. Cell OB 99' 14 1/2" J.P. 250' 0" A.P. 46'

F.H. 3 B.H. C.m. Lays a C.P. Q 100 B/B F 24'

W.D. 8.1

W.D. 8.1

W960-0097